

## **Correspondence Management System**

Control Number: AL-14-000-0576

Printing Date: November 08, 2013 10:04:52



Citizen Information

Citizen/Originator: Boehner, John A

Organization:

U.S. House of Representatives

Address:

1011 Longworth House Office Building, Washington, DC 20515

Constituent:

Wagner, Thomas R

Organization:

N/A

Address:

6290 Stillwell Beckett Rd, Oxford, OH 45056

Committee:

N/A

Sub-Committee:

N/A

Control Information

**Control Number:** 

AL-14-000-0576

Alternate Number:

N/A

Status:

Pending

Closed Date:

N/A 0

Due Date:

Nov 21, 2013

# of Extensions: Received Date:

Oct 29, 2013

Letter Date:

Oct 28, 2013

Addressee Org:

N/A

Addressee:

N/A LTR (Letter)

Priority Code:

Normal

Contact Type:

AA-OSWER-Assistant

Signature Date:

N/A

Signature:

701 GGVVEIT / Topiciant

Administrator - OSWER

File Code:

404-141-02-01\_141\_a(2) Copy of Controlled and Major Correspondence Record of the EPA

Administrator and other senior officials - Electronic.

Subject:

WHETHER THE COAST GUARD CUTTER, STORIS, HAVING TOXIC SUBSTANCES

ABOARD WOULD FALL UNDER THE TOXIC SUBSTANCES CONTROL ACT OF 1976

Instructions:

CLO - The closing line of all letters should state the following: "Again, thank you for your letter. If you have further questions, please contact me or your staff may contact (OCIR staff person) in EPA's Office of Congressional and Intergovernmental Relations at (insert OCIR email) or

(OCIR contact's phone number)

Instruction Note:

PLEASE PREPARE A RESPONSE FOR THE TROY, OHIO OFFICE

General Notes:

N/A

CC:

Carolyn Levine - OCIR-CA-WET R5 - Region 5 -- Immediate Office

Sven-erik Kaiser - OCIR-CA-WPTT

Lead Information

Lead Author:

N/A

Lead Assignments:

Assigner	Office	Assignee	Assigned Date	Due Date	Complete Date
Cassaundra	OCIR	OSWER	Nov 7, 2013	Nov 21, 2013	N/A
Eades	Instruction: N/A				
Bernadine Lon-	OSWER	OSWER-ORCR	Nov 7, 2013	Nov 19, 2013	N/A
don	Instruction: N/A				

Supporting Information



# Correspondence Management System Control Number: AL-14-000-0576

Printing Date: November 08, 2013 10:04:52



Supporting Author: N/A

Supporting Assignments:

Assigner	Office	Assignee	Assigned Date
.0		No Record Found.	

## History

Action By	Office	Action	Date
Cassaundra Eades	OCIR	Assign OCSPP as lead office	Oct 29, 2013
Zelma Taylor	OCSPP	Accepted the group assignment	Oct 29, 2013
Zelma Taylor	OCSPP	Assign OCSPP-OPPT as lead office	Oct 29, 2013
Lindsay Moose	OCSPP-OPPT	Accepted the group assignment	Nov 5, 2013
Lindsay Moose	OCSPP-OPPT	Sent to Zelma Taylor for Reassignment Request	Nov 5, 2013
Zelma Taylor	OCSPP	Sent to Cassaundra Eades for Reassignment Request	Nov 6, 2013
Cassaundra Eades	OCIR	Changed Signature AA-OCSPP-Assistant Administrator - OCSPP AA-OSWER-Assistant Administrator - OSWER	Nov 7, 2013
Cassaundra Eades	OCIR	Request for Reassignment Approved	Nov 7, 2013
Cassaundra Eades	OCIR	Assign OSWER as lead office	Nov 7, 2013
Bernadine Lon- don	OSWER	Accepted the group assignment	Nov 7, 2013
Bernadine Lon- don	OSWER	Assign OSWER-ORCR as lead office	Nov 7, 2013

### Comments

Commentator	Comment	Date
Lindsay Moose	This letter concerns ship disposal and as such should be reassigned to OSWER. Thank you.	Nov 5, 2013
Zelma Taylor	This letter concerns Ship Disposal and should be re-assigned to OS-WER. The CMS user making the request is Lindsay Moose	Nov 6, 2013

JOHN A. BOEHNER SPEAKER OHIO H-232 U.S. CAPITOL BUILDING WASHINGTON, D.C. 20515 (202) 225-0600



## Congress of the United States Biouse of Representatives

WASHINGTON OFFICE:

1011 LONGWORTH HOUSE OFFICE BUILDING WASHINGTON, DC 20515-3508 (202) 225-6205

DISTRICT OFFICES:

7969 CINCINNATI-DAYTON ROAD, SUITE B WEST CHESTER, OH 45069 (513) 779-5400

12 SOUTH PLUM STREET, 2NQ FLOOR TROY, OH 45373 (937) 339-1524 DISTRICT TOLL FREE NUMBER 1-800-582-1001

October 28, 2013

Congressional Inquiries
Congressional Liaison
Environmental Protection Agency
1200 Pennsylvania Avenue, NW
Room 3426 ARN
Washington, DC 20460-0003

Dear Congressional Liaison:

The enclosed correspondence, regarding whether the Coast Guard Cutter, Storis, having toxic substances aboard, would fall under the Toxic Substance Control Act of 1976, as it is being dismantled, scrapped and exported to Mexico on 10/29/2013, was sent to me by Thomas Wagner.

I would greatly appreciate your providing my Troy office with any appropriate information so that I can reply to my constituent.

If I can provide additional information, please do not hesitate to call me.

Sincerely,

John A. Boehner

JAB/ah



## Congressman John A. Boehner **U.S. House of Representatives** 1-800-582-1001

1011 Longworth H.O.B.

7969 Cincinnati-Dayton Road 12 South Plum Street

Washington D.C 20515 (202) 225-6205

West-Chester Ohio 45069 Troy, Ohio 45373 (513) 779-5400

(937) 339-15247

12 South Plum Street

Troy, Ohio 45373

EPA To: Liaison	From: Angle H	larrah
	o Frank I	DeBrosse
Fax: 20 2 50/ 1519	Pages:	
Phone:	Date: QCt 28,	<i>3013</i>
Re:	CCı	
Urgent   For Review   Pleas	Comment   Please Reply	, DFYI

ecomments: Coast Guard Cutter Storis-Conformal heports of lencapsulated PCB's absard. Ship is being dismantled + towed out the U.S. on 10/29. Constituent would like to know if this would fall under the Toxic Substances Control Act of 1976 - Dismantling, Scrapping + towing (exporting)

If there is a problem with this fax, please call 1-937-339-1524

# PRIVACY ACT RELEASE FORM PLEASE PRINT CLEARLY

City/State/Zip:	County
Phone #: Home	Work ()Other ()
Email Address:	
Places and completed f	orms to: Congressman John Boehner
Residents of Butler and Preble Counties: 7969 Cincinnati-Dayton Road	Residents of Clark, Darke, Mercer, and Miami Counties 12 South Plum Street
West Chester, Ohio 45069	Troy, Ohio 45373
	1974 (Title 5, Section 552A of the United States Code) aking an inquiry on your behalf. Completing and signing this
form authorizes Rep. John Boehner and hi	s staff to make inquiries to the appropriate officials on your
behalf and to release information to him or	his staff.
	8
To begin your inqu	uiry, provide all pertinent information:
Federal Agency Involved:	
Social Security Number:	Date Of Birth:
Military ID#:	Veteran's Claim #:
Military Branch, Rank & Unit:	
Alien #: ACIS/DC	OS Receipt #:
Immigration Petitioner's Name:	
Ranaficiary's Name	
Delicitaty 5 17ame.	
Desicional y Stratut.	
Other Numbers Identifying your claim:	
Other Numbers Identifying your claim: Please briefly describe your situation and t	he action or result or the information desired. Use the back of
Other Numbers Identifying your claim: Please briefly describe your situation and t	
Other Numbers Identifying your claim: Please briefly describe your situation and t	he action or result or the information desired. Use the back of
Other Numbers Identifying your claim: Please briefly describe your situation and t	he action or result or the information desired. Use the back of
Other Numbers Identifying your claim: Please briefly describe your situation and t	he action or result or the information desired. Use the back of

01/11/2013



## Memorandum

Subject: HAZMAT SURVEY OF CGC STORIS

Robert McMenamin, CG YARD

Date: 15 NOV 2000

5100

Reply to

sm-110 R. McMenamin

410-636-3772

To: Commandant, G-CFM-3

 The Coast Guard YARD was requested to conduct a Hazmat Survey on the CGC STORIS in Ketchican AL. POC was LT. K. Smyth (EO). The survey was conducted on 8/10/00. All compartments that were accessible were surveyed. The results of the survey showed that the vessel does contain Polychlorinated Biphenyl's materials.

In addition, the survey showed no asbestos containing material on the vessel but an asbestos removal was underway during the survey.

NAD - No Asbestos Detected

Sample #	Location	Material Tested	Result
A-5	Passageway, 02-59-2, Port BKHD Insulation	Cork	NAD
A-6	Boiler Flat, Port Pre-Heater, COV Insulation	White fibrous material	NAD
A-7	Outside Repair 3, OVHD, 2" Pipe Hanger	Gasket, White cloth	NAD
A-8	Emergency Generator Room, Starboard BKHD, behind switch 1- 161-1	Cork	NAD

 Lead base paint (LBP) was found on the exterior and interior surfaces of the vessel. Results greater than 1.0 mg/cm² is considered lead based paint.

Sample#	Results	Location	Outer Paint Layer
1886	0.0	Bridge, Mid BKHD	Beige
1887	0.2	Bridge, Fire Extinguisher, 02-85-1	Red
1888	0.0	Bridge, Aft, Portside, BKHD	White
1889	0.0	Bridge, Fog Signal Timer	Grey
1890	0.0	Bridge, Mid BKHD, Starboard, Electric Box	Blue
1891	8.3	Bridge wing, Starboard, under Gyro Repeater	Dark Grey
1892	0.0	Bridge wing, Starboard, forward BKHD	White

## Subj: HAZMAT SURVEY OF CGC STORIS

5100 15 NOV 2000

1893	0.0	02 Deck, outside, Starboard under ladder to 03 deck	White
1894	0.0	02 Deck, Aft ladder	Black
1895	0.0	Bridge wing, portside under Gyro Repeater	Dark Grey
1896=	0.0	Main Mast	SPAR
1897	0.0	03 Deck, portside antenna, HF Transmitter	Blue
1898	0.0	03 Deck, portside antenna, HF Receiver	Red
1899	0.0	Radio Rm., Starboard steel plate	White
1900	0.0	Fantail, FO vent, center	Yellow
1901	0.9	Fantail, port antenna	Red
1902	0.0	Fantail, Starboard capstan	SPAR
903	0.0	Starboard Deck, FO vent	Yellow
904	2.6	Paint Locker, Aft BKHD, Starboard side	White
905	VOID		
906	VOID		
907	0.0	Paint Locker, Deck	Dark Grey
908	4.3	Windlass Room, Aft BKHD	White
909	6.5	Windlass Room, Deck	Dark Grey
910	3.7	WTD to Lamp Locker	Green
911	4.3	WTD to Bos'n Locker	Red
912	10.0	Buoy Deck, Forward BKHD	White
913	0.0	Buoy Deck, Deck	Dark Grey
914	0.1	Buoy Deck, Safety lines around Main Hold Hatch	Yellow
915	0.0	MPA Stateroom, door	Brown
916	16.0	Refrigeration Machinery Space, 3-84-02-E, Aft BKHD	White
917	0.0	Crews Berthing, 2-84-0-L, column	White
918	7.5	Crews Berthing, Vent Cover, 2-110-2	White
919	0.0	Crews Berthing, 2-63-02-L, Aft BKHD	Yellow
920	0.0	Crews Berthing, 2-63-02-L, Portside Hull, Insulation Primer	Olive Green
921	VOID		
922	2.9	Repair 2, Starboard hull	Yellow, Zinc Chromate
923	0.0	Engine Room, CME, LO Filter	Grey
924	3.7	Engine Room, Port Hull	Dark Red
925	0.0	Main Motor Room, Main Motor	Grey
926	0.0	Main Motor Room, Frame for Main Motor	Red

The following areas (listed by sample number) were tested for PCBs. All results above
of 50 ug/g (ppm) is considered PCB containing/contaminated for regulatory purposes.

### ND - Non Detected

Sample#	Results	Location	Material	Picture#
1768	ND	Bridge, Forward BKHD, Deck Mat	Black Rubber	1
1769	ND	Bridge, Forward BKHD, Deck Mat	Blue Rubber	1
1770	ND	Incinerator Room, Aft BKHD, Cable Hanger	Black Rubber	2
1771	ND	Radio Room, Floor Mat	Blue Rubber	3
1772	ND	CO's Head, Pipe Insulation	Black Foam	4
1773	ND	Passageway 01-95, Deck Mat	Black Rubber	5
1774	ND	Boiler Flat, Starboard OVHD, 3/4" Fuel Line, Pipe Hanger	Red Rubber	6
1775	ND	Buoy Deck, Sewage Connection, Portside, Flange Gasket	Black Rubber	7
1776	ND	Female Head, OVHD, Vent Gasket	Black Rubber	8
1777	ND	Recreation Room, Seat Cushion	Brown Vinyl	9
1778		Recreation Room, Seat Cushion	Blue/Green Foam	9
1779	ND	Recreation Room, OVHD, 2" Fire Main, Pipe Insulation	Black Foam	10
1780	ND	Messdeck, under DC Plates, Pipe Insulation	Black Foam	11
1781	ND	Messdeck, Seat Cushion	Yellow & Green Foam	, 12
1782	ND	Messdeck, Seat Cushions	Blue Vinyl	12
1783	ND	CPO Head, Urinal Drain Line	Black Foam	13
1784	ND	CPO Head, CW Line to Toilet	Black Foam	14
1785	ND	CPO Head, CW Line over Sink, Pipe Hanger	Paper Gasket	
1786	ND	POI Head, HW Line over Sink	Black Foam	16
1787	3	Ships Office, OVHD, 1" Line	Black Foam	17
1788	ND	Ships Office, OVHD, 2" Line, Pipe Insulation	Black Foam	18
1789	ND	Emergency Generator Room, Day Tank, Hatch Gasket	Rubber/Cork	
1790	ND	Crews Berthing 2-84-0-L, Portside, Aft, Pipe Insulation	Black Foam	20
1791	ND	Crews Berthing 2-84-0-L, Portside, unpainted Pipe Insulation	Black Foam	21
1792	18	Refrigeration Machinery Space 3-84-02-E,	Grey Foam	22

Subj: HAZMAT SURVEY OF CGC STORIS

5100 15 NOV 2000

			Portside, Compressor Filters		
The second secon	1793	on the second	Reefer Flats, Non-skid	Non-Skid, Adhesive	2
	1794	NE	Crews Berthing 2-63-01-L, Seat Cushions	Dark Brown Foam	2
	1795	ND	Crews Berthing 2-63-01-L, Seat Cushions	Red Vinyl	24
	1796	ND	Crews Head 2-63-02-L, Water lines to Deep Sink	Black Foam	2.
	1797	140	Repair 2, Starboard, Pipe Insulation	Black Foam	20
	1798	ND	Repair 2, Carpet Mat	Felt (not Chromelock)	27
	1799	ND	DC Shop, Portside, 2" Pipe Hanger	Red Rubber	28
	1800		Engine Room, Starboard, Sewage Lines near FR 136	Black Foam	29
,	1801		Engine Room, Control Booth vent under Blower Switches, Insulation	Black Foam	30
	1802	5 81	Auxiliary Shop, OVHD, 2" Sewage Line, Pipe Insulation	Black Foam	31
	1803		Main Motor Room, FW Manifold, Pipe Insulation	Black Foam	32
	1804		Main Motor Room, Fire Pump#3, Pipe Insulation	Black Foam	33
	1805	-	Generator Room #3, Deck Mat	Grey Rubber	34
	1806		Aft Steering, Forward BKHD, Cable Hanger	Black Rubber	35

I trust this information will be sufficient for your purposes, but if you have any questions concerning this survey, please contact me.

ROBERT D MCMENAMIN

Copy Commandant, G-SEN
Chief, Planning and Marketing, CG YARD
EO, CGC STORIS

John Hometrowed -destructino@embarqmed.comp.@ To: Sarah Papa -ampaina@itea.neb., "space" -appaina@tase.neb., Thirecourse@gmeLoan Red: Fard: First: CGC STORKS - stagesty exported with PCBs

5 Attachments, 2.8 MB

Forwarded Message
From: John Newskershit Gestputrol@embarquesd.com>
To: Mark Chyan Mack@mall house gov , Nation Facey @ensall.com>
Cr. Jon A. Otman (Jon.chmen@ensall.com>
Sent; Mon, 28 Oct 2013 06:48:10 -0400 (EDT)
Subject: Fwd: Fwd: CGC STORIS - Riegally exported with PCBs

The Last Patrol needs the assistance of the Senate and Congressional members from Ohio in regards to the ex-USCGC Storts. Sonator Begich's office has also been contacted

Please find attached documentation and converpondence regarding the high likelihood that CGC STORIS was allowed on Friday to be toward from the Sulsun Bay recipited fiest and eleaned for export to Mexico for scrapping even though she contains encapsulated PCBs on board. This export would be in violation of the Toxic Substances Control Act of 1975 and importing the material into Mexico would violate the Basel Convention.

We have enlisted legal exsistance in the master and are entempling to stop the ship from leaving the country. You can see by the small tread below and the attached information the there is more then a good likely hood that GSA has not complied with the law. Once this has been verified we feel the sale contract of the ship should be recinded and the ship returned to the mothball fleet. The people listed below can give all the back up documentation on this losue. Thank you for your help.

Best Regards

Tokedo Ohio

Contact into for the parties involved are: Potly Parks - (804)410-2168 - Cell (703)338-6881 - email: polly parks@emngroup.com

attorney Denise Repp. Cell- (202) 546-2533

Jon Ottman - (586)322-5817, Historical preservationist for the Last Patrol

- Original Message --

Subjects Perd: Perd: Story on the Storie

DesiraSac, 26 Oct 2013 18:33:04-0500 (CDT)
Prestablish Ministers Supristing Systems

Reply To: porismusus fiverion mi

FYI

Storis Museum clo Jim Loback, 10436 Yeal Clicib, Fountain Valley, CA 82706 Tel 714 908 9984, www.storismuseum.org storismuseum@pe@zpn.mt

-- Original Massaco

From: Jav Barrett

Date: Oct 28, 2013 11:08:31 AM

Subject: Fwd: Stary on the Starie

To: stodsmuseum@nertzon.not

Jav Barrett

KNAXT Resilo

#### Bogin forwarded message:

- > From: "Polly Perks" < Polly Parks Camponne comp
- > Bubject: Story on the Storis
- > Date: October 25, 2015 at 2:36:35 PM AKOT
- 10 AV 6410 OF 10
  - > Destr Jay,
  - > This story has logs, Whors I read your report in the Store and Eidpers this a.m., I find off on exact to Still Neggies at EPA HC as to whether the UROG, QSA, or the unidentified buthersman hale gibter a got expert verticer as TECA does not allow fine suport of PCRs allows 80 ppm and I (first everyone is my company who works on excepting stigs for the US Newy, MARAC), and commercial versacing, process these add other have puts in them. I got in touch with the UBCG and GSA representations listed on the gas austice also glists below) and stated if they or the businessem... If just attach everyfilling it aposts for Real (real life. Beach stampted to call back the hastmat report, but too table, This is background. You can't do you seen laguest, though they will know I gave you the PCB report. I have nothing back from EPA HQ or Region PC, to I have to uniformately suspect they were gasting ready to stip off beard upon that PCB report but states explicitly that exceptionated PCBs were not removed. Both HQ and Region DC traves better, if that ship is going to be accepted, I needs to be accepted in the UB.
  - > So the GSA audion into mattes essuer in the explanation the inference is the vessed is functional, not obsolete; housese, it is of note that GS Insignit were removed, that shear they knew it would be excepted outside the LSS because there is no need to do that in the US. No ecition of iscorate or disk pole might be involved. GOS clarks audion shows the two bold (probably one bidder with an explanation relian) and Storia bid instory explains a Sible repro of the bid process.
  - > Let not know if you have any questions, I work out of my house so the 804 member works, but fin on eastern time.
  - > Polly Perfes
  - > T: +1 (804)410-2168
  - > M: +1 (703)336-6881
  - > F: +1 (804)410-2188
  - > 5: роду выполняющими сою «предоходу свядения полических
  - > A: EMR USA Southern, Washington DC Office, 216 Spotswood Lane, Colonial Beach, VA 22443
  - > และ.อาการกระทา < <u>(ชาวะโมละ อาการกระท</u> ออกา
  - ii S
  - > This electronic message contains information from EMR which may be privileged or confidential.
  - > The information is intended to be for the use of the individual(s) or entity partied above.
  - If you are not the intended recipient be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited.
  - If you have received this electronic message in error, please notify us by telephone or small (to the numbers or address above) immediately.
  - > Adivity and use of the BMR IS-mail system is monitored to secure its effective operation and for other lawful business purposes.
  - Communications using this system will also be monitored and may be recorded to enoure effective operation and for other travial business purposes.
  - > European Metal Recycling Limited is a company, registered in England and Wales, registered rember 2954823,
  - > registered office Striue House, Delte Creacent, Westbytook, Warrington, WAS 7NS, United Kingdom.

Howey Storis Museum Follow,

I am trying to pass this on to Jos Goldhof, who I interviewed this week about the Stanta. Egot the e-mest below in response to it and wanted to pass it on. Let me took if there is a better or med to reside, Jets.

hanks.

Jay Barrett KMXT Radio

Begin forwarded massage;

Fronc "Poly Parks" «Colly Page Centratous Costs
Subject Story on the
Storia
Date: October SS, 2019 at
25955 Pile Alphamaticillust.cop

Door Joy,

This story has logs. When I read your report in the Baars and Silepes this si.m., I sted off an exact to SIR Neggle of SPA HC as to whether the USCC, GSA, or the undeptitud businessment had poten a plot open without as TECA doos not allow the support of PCBs allows 60 ppm and I (red everyone in the open and commoncial ventually, areas these the subject and commoncial ventually, areas these of the HC size and GSA representatives sized on the gene auction site (first before) and select of the gene auction site (first before) and select sized on the gene auction site (first before) and select sized on the gene auction site (first before and select site (first before) and select sized on the genetic size fixed (first before) and select sized on the genetic sized from size fixed on the pectors of least (first before) and select sized on the genetic sized sized from sized sized on the supposed of the becompany of the sized sized

Bo the GGA audion into numers series: In the auptention the between in the vensel in functional, not obtained; however, it is of reals that CG insignia water carrowed, risk than they share it would be composed outside the US because there is no need to do that in the UR. No relies of harmales or that point might be involved. CGC Blooks suction shows the two block (probably one bloder with an eutomatic state) and Stooks pick history despitate a little store of the bid processa.

Let me leade if you have any questions. I trook out of my house so the 804 number works, but I'm on eastern time.

Poty Parks

T: +1 (804)410-2168

64 +1 (703)338-6881

F: +1 (804)410-2100

E: poly partici@emrytoup.com < putitic polly.parks@emrytoup.com

A: EMR USA - Southern, Waskington DC Office, 216 Spotswood Lane, Coloniai Beach, VA 22443 USA @MOCCUE. 2631 4/18/2018.cm/26018.5604

This electronic message contains information from EMR which may be privileged or confidential.

The information is intended to be for the use of the individual(s) or entity nemed above.

If you are not the intended recipions be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited.

If you have received this electronic message in error, please notify us by telephone or erredl (to the numbers or eddress above) immediately. Communications using this system will also be monitored and may be monitored and may be monitored and may be monitored system spention and for other band bushess purposess.

European Statistal Respecting Limitor is a company, registered in England and Wildow, supplied and Wildow, s

Section State and a Condition Kin

cOvily and use of the Elish E-mail system is a secure its effective operation and for other t

## MOTICE OF AWARD

#### (SALE OF GOVERNMENT OWNED PERSONAL PROPERTY)

CONTRACT NO:

GS04F13FBB9671

DATE: 06/28/13

INVITATION NO: 4109CT13425

PURCHASER: BIDDER NO.: 232542 US WETALS RECOVERY INC 7928 AIRMAY ROAD

SAN DIEGO

CA 92138

TEL: (619)823-5925 MARKINUSWETALS.US

YOUR BID FOR THE POLLOWING LISTED PROPERTY HAS BEEN ACCEPTED. PAYMENT OF BALANCE MOST BE RECEIVED ALONG WITH THE SECOND COSY OF THIS MOTICE AND PROPERTY MOST BE REMOVED BY DATES SPECIFIED IN THIS CONTRACT, UPON RECEIPT OF FULL DAYMENT, A RECEIPT OF PRYMENT WILL BE PORMANDED TO YOU TO PRESENT TO CUSTODIAN AS AUTHORITY TO REMOVE THE PROPERTY.

#### CONTRACTING OFFICER

AND SECURE THE PERSON AND SECURE AND SECURE

DATE

LOT NO.

DESCRIPTION

QUANTITY UNIT

9 70

1942 UNITED STATES COAST GUARD STORIS (WMSC-36),
MONE/MANUFACTURER: DOLENO SHIPPULLDING, MODEL:
SUPPLY SHIP, DATE OF MANUFACTURER, APAIL 4, 1942,
VESSEL MAME: USCCC STORIS, HOLL NO: WMSC-38,
SEAWORTHY: WES, VESSEL LENGTE: 230, ENGINE
MISSING: NO, ENGINE HOURS: INDONOMN, MARINE
SURVEY: NO, THIS VESSEL IS A MEDIEM ENDURANCE
CULTER WHICH WAS USED FOR DAY ENFORCEMENT AND
FISHERIES: CUTTER IS EQUIPPED WITH THREE EMD
645EG ENGINES

CONNECTED TO THREE WESTINGHOUSE DC GENERATORS
... CONTINUED AS SHOWN ON INVITATION FOR BID

PARMENT INFORMATION:

PAYMENT MUST BE MADE BY:

07/01/13

UNIT PRICE:

70100.00

PROPERTY MUST BE REMOVED BY: 07/12/13

DEPOSIT RECEIVED:

70100,00

APD PA: CHIENES

BALANCE DUE GOVIT

70100.00

SELLING AGENCY:

BOT LOCATION:

OSA, PAS, 40SCC U.S. MARTITIME BEADY RESERVE PLEST SALES OFFICE, STE. 130 BND OF LAKE BERMAN RORD

SALES OFFICE, STE. 130 77 FORSYTH STREET ATLANTA

BENICIA

GA. 30202 SALES MANAGER CA 94510 JEFF BEACH

TEL: (404)331-0040 FAX: (404)331-7584

DEL: (202)372-3646 RAX: (202)372-3545





Home

All Categories

Real Estate

Offline Sales

Warning: In order to view the most up-to-date information, please click the refresh button on your browser.

#### item information

#### CGC STORIS (WMEC-38) MEDIUM ENDURANCE CUTTER

Sale-Lot Number: 41QSCI13425001

City, State: Benicia, CA

Current Bid: 70,100 USD (Reserve Not Met)

Al: Categories

Bidders: 2

Close Time: 06/27 08:15 PM CT (Closed)

Time Remaining:

Description Bidding Details Bid History

Note: When "Compatible" bidding occurs (two or more bids of the same amount are submitted), the "high bid" is determined by GSA Auctions system's evaluation, based on the time of submission and/or by proxy.

To enhance bidder privacy, and protect GSA Auctions users from fraudulent erraits, GSA Auctiona has changed how User IDs are displayed on the bid history page. Only you can view your User ID, all other members will see anonymous user IDs, such as Bidder\*.


As of February 14, 2009 bidders will be assigned the actual bidder number for the sale/lot based on when they placed their bid, if you are the first bidder for this sale you will see Bidder#1, if you are the second bidder you will see Bidderif2.

### Bidders in the Auction (Current top 10 bidders)

Bidder		Bid	Amount		Data-Time
Bidder#2	(Rese	erve not mat) 70,1	00 USD	08/27/2013	07:55:58 PM CT
Bidden#1		69,1	00 USD	06/27/2013	07:55:21 PM CT
Your Bids					
D1d 0	Std Amount	Max Limit	Status		Date
No bids cur	rently				


#### (\*) Possible Extension, See Bidding Rules.

#### Item Photos



#### Item Location

NOTE: Maps are not updated frequently and are likely to miss new addresses or show incorrect addresses. Please visit http://maps.google.com or http://www.mapquest.com for accurate property location and directions.



#### Go Green... Reuse is Recycling!

Carbon savings for this item are not available.

CONTRACTOR CONTRACTOR TO THE SECOND SECOND Select an Equivelency: Gallons of Gasoline Used

Click here for additional information.

About GSA Auditors Help FAQ Sales Abbreviations RSS Credit Card Form Federal Acquistion Service GSA Fleet Vehicle Seles GSA Surplus Seles Real Property Disposel Public Buildings Service

Terms & Conditions Protecting Your Privacy Accessibility Policy System Status Browner Support

Contact Us

Copyright @ 2001 U.S. General Services Administration



Home

All Categories

Real Estate

Offline Sales

All Categories

Warming: In order to view the most up-to-date information, please click the refresh button on your browser.

#### CGC STORIS (WIMEC-38) MEDIUM ENDURANCE CUTTER

Sale-Lot Number: 41QSCI13425001

City, State: Benicia, CA

Current &d: 70,100 USD (Reserve Not Met)

Bidders: 2

Close Time: 08/27 08:15 PM CT (Closed)


Time Remaining:

Description Bidding Details Bid History

#### BID DEPOSIT REQUIRED: \$20,000.00

1942 UNITED STATES COAST GUARD STORIS (WMEC-38), MAKEMANUFACTURER: TOLEDO SHIPBUILDING, MODEL: SUPPLY SHIP, DATE OF MANUFACTURER: APRIL 4, 1942, VESSEL NAME: USCGC STORIS, HULL NO: WMEC-38, SEAWORTHY: YES, VESSEL LENGTH: 230, ENGINE MISSING: NO, ENGINE HOURS: UNKNOWN, MARINE SURVEY: NO, THIS VESSEL IS A MEDIUM ENDURANCE CUTTER WHICH WAS USED FOR LAW ENFORCEMENT AND FISHERIES, CUTTER IS EQUIPPED WITH THREE EMD 645EG ENGINES CONNECTED TO THREE WEST INGHOUSE DC GENERATORS PROVIDING POWER TO ONE WESTINGHOUSE DC PROPULSION MOTOR (1800 HP)CUTTER REPOWERED IN 1988. PROPELLER IS 10 FEET-6 INCHES IN DIAMETER X 7 FEET-4 INCHES PITCH, 6 BLADE RH BRONZE, HULL IS RIVETED STEEL, FULL LOAD DISPLACEMENT IS 1710 LONG TONS. SHAFT BEARING FORWARD, ORION THRUST SHAFT BEARING AFT, THORDON, SHAFT SEALS FORE AND AFT: JOHN CRANE TYPE MXB, TANK CAPACITY DIESEL OIL 324 LONG TONS, FRESH WATER: 63 LONG TONS, COAST GUARD CREW SIZE: 10 OFFICERS AND 66 CREW MEMBERS WITH SEPARATE CREW QUARTERS FOR BOTH MEN AND WOMEN. LAST DRY DOCKING OF CLITTER WAS IN 2007 PRIOR TO ENTRY INTO THE READY RESERVE FLEET. HULL WAS CLEANED AND HULL RECOATED TO PREVENT SLUFFING OF HULL PAINT, THE TWO, 22 FOOT, MODEL HISSO ZODIAC BOATS CURRENTLY ON BOARD THE CUTTER WILL CONVEY WITH THE CUTTER BOAT HIN: XDC63248C000 AND XDC63193E898. CUTTER ALSO EQUIPPED WITH A HYDRAULIC CARGO BOOM ON FORWARD PART OF THE CUTTER. CUTTER WAS ORIGINALLY DESIGNED TO BE A SUPPLY VESSEL FOR OPERATIONS IN GREENLAND (NORTH ATLANTIC, THE CUTTER HAS SOME DEGREE OF ICE BREAKING CAPABILITY. SHIP CIRCUMENAVIGATED NORTH AMERICA VIA NORTHWEST PASSAGE WITH CGC CUTTERS BRAMBLE AND SPAR IN 1857. VESSEL ADDED TO THE REGISTER OF HISTORICAL PLACES IN DECEMBER 2012, CUTTER HOMEPORTED IN ALASKA 1990 UNTIL 2007 WHEN IT WAS REMOVED FROM ACTIVE SERVICE AND MOVED TO THE RRF, SUISUN BAY, CA. THE CONDITION CODE OF "REPAIRABLE" DUE TO REMOVAL OF SHIP ELECTRONICS AND ABSENCE OF WORKING RADIO OR WORKING RADAR. NEXT OWNER/OPERATOR WILL HAVE TO PROVIDE A VALID CERTIFICATE OF FINANCIAL RESPONSIBILITY (COFR) BEFORE : ACCEPTING CUSTODY OF THE CUTTER, NEXT OWNER/OPERATOR ALBO RESPONSIBLE FOR ANY REQUIREMENTS TO CLEAN HULL FOR COMPLIANCE WITH NON-INDIGENOUS SPECIES ACT BEFORE CUTTER DEPARTS SAN FRANCISCO BAY AREA ON BOARD INSPECTIONS ARE HIGHLY ENCOURAGED AND CAN BE ARRANGED BY CONTACTING JEFF BEACH AT USCG HEADQUARTERS IN WASHINGTON, DC AT (202) 372-3646, OR EMAIL: JEFF.L.BEACHQUSCG.MIL SHIP VISITS WILL A COUPLE OF DAYS ADVANCE NOTICE AND ARE SUBJECT TO ESCORT AVAILABILITY. THE PHOTO LISTED FOR THE CGC STORIS SHOWS CUTTER WITH FULL COAST GUARD MARKINGS AS THE SHIP TRAVELS UNDER THE GOLDEN GATE BRIDGE, ALL COAST GLIARD MARKINGS HAVE BEEN REMOVED FROM THE SHIP AND IT NOW HAS AN ALL WHITE HULL LAST DDX 2007. THIS ITEM REQUIRES A BID DEPOSIT OF \$20,000. BID DEPOSITS MUST BE IN THE FORM OF A CASHIER-S CHECK OR

#### item Photos



#### Item Location

NOTE: Maps are not updated frequently and are likely to miss new addresses or show incorrect addresses. Please visit http://mapa.google.com or http://www.mapquest.com for accurate preparty location and directions.



#### Go Green... Reuse is Recycling!

Carbon savings for this item are not available.

Select an Equivalency: Gallons of Gasoline Used

Click here for additional information.

MONEY ORDER AND SHOULD BE MADE OUT TO G.S.A. AND MALED TO: G6A, 4Q8CA, 77 FORSYTH STREET, SUITE 100, ATTN: TONYA DILLARD, ATLANTA, GA 20303. PROSPECTIVE BIDDERS MUST PROVIDE THEIR GSAAUCTIONS LOGIN NAME, SALE AND LOT NUMBER, ADDRESS, TELEPHONE NUMBER, AND EMAIL ADDRESS. ONCE BID DEPOSIT HAS BEEN RECEIVED, BID RIGHTS WILL BE ASSIGNED\*\*\*\*ALL BID DEPOSITS WILL BE RETURNED , WITHIN FIVE BUSINESS DAYS FROM THE CLOSING DATE OF THE SALE. ALL BIDDERS MUST BE REGISTERED ALL BID DEPOSITS MUST BE RECEIVED BY 12 NOON ON JUNE 26, 2013\*\*\*\* ALL BIDDERS MUST BE REGISTERED VIA GSAAUCTIONS.GOV WEBSITE\*\*\*\*\*CREDIT CARDS WILL NOT BE ACCEPTED FOR BID DEPOSITS\*\*\*\* REPAIRS MAY BE REQUIRED\*\* STARTING JUNE 20TH THRU JUNE 27TH, POTENTIAL BIDDER MAY CALL CAPTAIN PATRICK FLYNN AT 202-372-3862 TO OBTAIN INFORMATION OR SCHEDULE APPOINTMENTS .....

THE CONDITION OF THE PROPERTY IS NOT WARRANTED.

Click here for pricing guides.

2700983127L001A--

SPECIAL INSPECTION INFORMATION

POTENTIAL BIDDERS ARE URGED TO INSPECT THE VESSEL PRIOR TO

PLACING A BID. PROPERTY MUST BE PAID FOR NO LATER THAN

JULY 1, 2013.

Please contact the custodian for inspection dates and times and for removal arrangements.

PROPERTY REMOVAL: Due to security issues at property locations, successful biddens are required to contact the custodian prior to entering the facility to remove property, and at times, they are not permitted to use security phones. Therefore, successful bidders must communicate with the custodians in advance to make arrangements for removal and/or have a cell phone with them to contact them once they arrive at the secured location.

Successful bidders are cautioned that they will be responsible for loading, packing and removal of any and all property awarded to them from the exact place where the property is located, as

Property Location and Inquiries/questions regarding property inspection and/or removal:

U.S. Maritima Ready Reserva Fleet End Of Lake Herman Road Benida, CA 94510

Contect; Jeff Beach Phone: 202-372-3646 Fax: 202-372-3945 JEFF.LBEACH@USCG.MIL

For inquiries/questions regarding payment, contact the following sales office:

GSA, FAS, 4QSCC SALES OFFICE 77 PORSYTH STREET ATLANTA, GA 30303

Phone: 404-331-0040 Fax: 404-331-7584

For inquiries/questions regarding contractual leaves, contact the following sales contracting officer/property disposal specialist:

Federal Acquisition Survice

**GSA Fleet Vehicle Sales** 

Public Buildings Service

**GSA Surplus Sales Real Property Disposal** 

TONYA DILLARD Phone: 404-331-0535 TONYA DILLARD@GSA.GOV

(\*) Possible Extension. See Bidding Rules.

About GSA Auctions Help

FAQ

RSS

Credit Card Form

Contact Us

Copyright © 2001 U.S. General Services Administration

Terms & Conditions

Protecting Your Privacy Accessibility Policy

System Status

Browser Support

Attachments can contain viruses that may harm your computer. Attachments may not display correctly.

#### **Polly Parks**

From:

Polly Parks

Sent: Fri 10/25/2013 11:05 AM

To:

rollins.christopher@epa,gov

Cc:

Chris Green; Jason Glascock; Tony Schultz; Tara Tomaslewicz.

Subject:

RE: Sale of 1942 USCG Storis for scrapping in Mexico

Attachments: Storis pcb report pdf(2MB)

Dear Chris.

We are in receipt of the report. Page one, only those PCBs not encapsulated were certified as removed. Sorry Region IX got stuck with a hot federal potato again. Let us know if there is anything we can do to help.

#### Polly Parks

T: +1 (804)410-2168 M; +1 (703)338-6881 F: +1 (804)410-2168

E: polly.parks@emrgroup.com

A: EMR USA - Southern, Washington DC Office, 216 Spotswood Lane, Colonial Beach, VA 22443

usa,emrgroup.com

From: Polly Parks

Sent: Fri 10/25/2013 10:20 AM To: rollins.christopher@epa.gov

Cc: Chris Green; Jason Glascock; Tony Schultz; Tara Tomaslewicz Subject: FW: Sale of 1942 USCG Storis for scrapping in Mexico

Dear Chris,

I hope all is well. I understand you are looking into the UCG Storis which was sold to an unidentified businessman to be scrapped in Mexico. I've cc'd our environmental staff who can help you interpret whatever was sent over by the USCG to certify the 1942 build was indeed PCB-free. Our experience is that is impossible unless the vessel is dismantied; however, if the USCG has indeed developed a methodology that allows for the removal of all gaskets, etc. that are integrated into the construction without dismantlement, as long as it is cost-effective, we are, of course, eager to apply it commercially.

Best regards,

Polly Parks

T: +1 (804)410-2168 M: +1 (703)338-6881 F: +1 (804)410-2168

E: poliv.parks@emrgroup.com

A: EMR USA - Southern, Washington DC Office, 216 Spotswood Lane, Colonial Beach, VA 22443

usa.amrgroup.com

From: Beach, Jeff L CIV [mailto:Jeff.L.Beach@uscg.mif]

Sent: Fri 10/25/2013 9:54 AM

To: Polly Parks; 'TONYA.DILLARD@gsa.gov'

Cc: 'william.noggle@EPA.GOV'

Subject: RE: Sale of 1942 USCG Storis for scrapping in Mexico

Ms Parks

Yesterday I forward to Mr. Chris Rollins of your San Francisco office a copy of the 2000 HAZMAT report on CGC

STORIS which did identify the presence of PCB material and a copy of the 2007 report that confirmed that the PCB material had been removed from the cutter and that the CGC STORIS was now PCB free.

Jeff Beach, CPPM
Manager of Retired CG Boats & Decommissioned Cutters
USCG Headquarters @ ST "E" Campus
(202) 372-3646

----Original Message----

From: prvs=0034ca9bc=Polly.Parks@emrgroup.com [mailto:prvs=0034ca9bc=Polly.Parks@emrgroup.com] On

Behalf Of Polly Parks

Sent: Friday, October 25, 2013 9:36 AM

To: Beach, Jeff L CIV; TONYA.DILLARD@gsa.gov

Cc: william.noggle@EPA.GOV

Subject: Sale of 1942 USCG Storis for scrapping in Mexico

Dear Mr. Beach and Ms. Dillard,

I noticed the article in the Stars and Stripes this a.m. about the sale by the GSA for the USCG of the UGC Storis, which was nested at the SBRF; the article states the vessel is to be scrapped in Mexico. After visiting the GSA archive website and reviewing the solicitation, while it did mention the need to clean the vessel bottom to comply with the NISA, which means in drydock in the Bay Area, it did not mention that if bought for scrap the vessel contained hazardous material and that given the age of the vessel, it is almost certain to contain PCBs that would be subject to the TSCA PCB export ban. Did the USCG or GSA apply for a PCB export walver prior to selling the vessel or was the successful bidder informed in writing, by your agencies that the vessel was subject to the PCB export ban? If this has not happened, the owner in all probability will be in violation of the TSCA export ban if the vessel is removed from the United States. Please let me, and Mr. William Noggle at the EPA, know what the status of the vessel, and who the successful bidder, is.

http://www.stripes.com/news/us/historic-coast-guard-cutter-headed-to-scrap-yard-1.248976#.Umpptxeby3w.emall http://gsaauctions.gov/gsaauctions/aucdscink?sl=410SCI13425001#.UmpyJ2CC8JM.email

Sincerely,

Polly Parks

T: +1 (804)410-2168

M: +1 (703)338-6881

F: +1 (804)410-2168

E: polly.parks@emrgroup.com <mailto:polly.parks@emrgroup.com>

A: EMR USA - Southern, Washington DC Office, 216 Spotswood Lane, Colonial Beach, VA 22443

usa.emrgroup.com <a href="http://usa.emrgroup.com/">http://usa.emrgroup.com/>

This electronic message contains information from EMR which may be privileged or confidential.

The information is intended to be for the use of the individual(s) or entity named above.

If you are not the intended recipient be aware that any disclosure, copying, distribution or use of the contents of this information is prohibited.

If you have received this electronic message in error, please notify us by telephone or email (to the numbers or address above) immediately.

Activity and use of the EMR E-mail system is monitored to secure its effective operation and for other lawful business purposes.

Communications using this system will also be monitored and may be recorded to secure effective operation

and for other lawful business purposes.

European Metal Recycling Limited is a company, registered in England and Wales, registered number 2954623, registered office Sirius House, Delta Crescent, Westbrook, Warrington, WA5 7NS, United Kingdom.

Trompil Condition FAR Subscripe Confusion Condition DC Amerika Frick Sales



All Categories

Real Estate

Offline Sales

C) SEARCH Advanced Search

LOGIN REGISTER

All Celecones >

Warning: In order to view the most up-to-date information, please click the refresh button on your browser.

CGC STORIS (WMEC-38) MEDIUM ENDURANCE CUTTER

Sale-Lot Number: 41QSCI13425001

City, State: Bericia, CA

Current Bid: 70,100 USD (Reserve Not Mel)

Bidders: 2

Close Time: 06/27 08:15 PM CT (Closed)

Description Bldding Details

Auction Description and Bidding Rules

This is an English suction. At the close of the auction, the user with the highest bid wins the auction, as long as that bid is at or above the auction's reserve price. The reserve price is the lowest price

Once you submit a bid, you cannot cancel it, but you can replace it with a higher bid. When you submit a new higher bid, it replaces your previous one.

Click the Bid History link to see the bids you have submitted in this suction (My Bids).

Auction Properties

Current High Bld: 70,100 USD (Reserve Not Met)

Reserve Price: true

Reserve Price Amount: N/A

Bid increment: 100 USD

inactivity period: 20

Run length: 15

Inactivity period for reduction of 2

Bid Increment:

Reduction of bid increment: 50

Reduction of bid Increment 100 USD

limit:

Start Time: 20130812 08:00 PM CT

Close Time: 06/27 08:15 PM CT

Closing Rules: This auction will end in one of these ways:

At the auction close time if no bids (proxy or flat) are placed within the inschilly period, or the auction is not subject to a

inectivity period.


After the inactivity period has passed without any bids (proxy or

flet) being placed.

Status: Closed

Note: "N/A" or a blank indicates that the value is not available for this auction.

Item Photos



#### Item Location

NOTE: Maps are not updated frequently and are likely to miss new addresses or show incorrect addresses. Please visit http://maps.google.com or http://www.mapquest.com for accurate property incetton and directions.



This site has exceeded ha daily quota for m are the creator of this site, please visit the documentation to learn more.

Go Green... Reuse is Recycling!

Carbon savings for this item are not available.

Select an Equivalency: Galtons of Gasoline Used

Click here for additional information.

#### How To Bid

#### Placing a Bid

GSA Auctions only accepts minimum and maximum bids. A maximum bid is the maximum amount you are willing to pay for an Item. Maximum bids are also referred to se proxy bids. When you place your maximum bid, GSA Auctions will use as much of your bid as needed to make you the current winner of the auction or to meet the auction's reserve price. The minimum bid you can place is either the starting price of the auction, or the current high bid plus the bld increment.

GSA Auctions only accepts bids in whole dollar amounts. Bids in partial dollar amounts, \$150,25 for example, will not be accepted by the USA Auctions system.

The reserve price is the minimum price that GSA Auctions is willing to accept for an item. If your maximum bid equals or exceeds the reserve price, your bid will be placed at the reserve price.

How Are Tie Bids Resolved in GSA Auctions? If a bidder places a bid with the same proxy bid amount as another bidder, the previous (first) bidder will have the current high bid since their bid was placed first. Both bids are recorded with the same amount, displaying the first bidder with the same amount as current high bid, until another bidder bids higher.

#### Competing Proxy Limits

When two proxy bids compete, the greater of the two proxy firrits always wins. If the greater proxy limit exceeds the lesser proxy limit by the bid increment, then a bid equal to the lesser proxy limit plus the bid increment will be placed. If the greater proxy limit does not exceed the lesser proxy limit by the bld increment, then the greater proxy limit's maximum bid will be placed.

#### Increasing Your Maximum Bid

You can increase your maximum bid if you are currently the winner in an auction. To increase your maximum bid, enter an amount greater than your current maximum bid. Increasing your bid will not increase your current blob bid.

#### Decreasing Your Maximum Bid

You can decrease your maximum bid if you are currently the winner in an auction. To decrease your maximum bid, enter an amount less than your current maximum bid. You cannot decrease your bid balow the minimum bid price.

#### Maximum Bld / Proxy Bld

Your maximum bid or proxy bid, submits bids on your behalf. You specify the maximum price you are willing to pay. If you are outbid, the system submits a replacement bid at a higher price to keep you in the suction. It will bid as much as your maximum bid but no more.

Your maximum price is not shown to any other biddens.

If the system reaches your maximum bid limit, it stops bidding for you. Submit enother bid it you want to continue bidding.

## Winning & Trading

The highest bid at the close of the auction wins.

If your bid is lower than the reserve price, you will not win the auction.

#### Reduction of Bid Increment Notes.

The reduction of bid increment happens when there is no bid activity within a specified time for an sudion. The system will decrease the incremental bid amount by a percentage upto a limit based on template codes designed for this purpose. All auctions are not subject to the reduction of bid increment rule. Here's an example: A bid increment is set at \$25.00 for an auction. A No-Bid-Period has been set for 2 days at a reduction rate of 10 percent and a reduction limit of \$20,00. After 2 tull days of inactivity for the auction, the bid increment will be reduced by 10 percent now making the current bid increment \$22.00. 10 percent of \$25.00 = \$2.50 rounded to the nearest datar \$3.00. The reduction is repeated for multiple inactivity periods until the reduction limit is reached or auction doses

#### (\*) Possible Extension. See Bidding Rules.

About GSA Auctions Help FAO

Federal Acculation Service GSA Fleet Vehicle Sales GSA Sumlus Sales Real Property Disposal

Tarms & Conditions Protecting You Privacy Accessinility Policy System Status Browser Support

Sales Abbrevations RSS

Public Bulldings Service Credit Card Form

Contact Us

Copyright © 2001 U.S. General Services Administration

#### **Polly Parks**

From:

Polly Parks

Sent: Fri 10/25/2013 11:24 AM

To:

Beach, Jeff L CIV

Cc:

'TONYA,DILLARD@gsa.gov'; roilins.christopher@epa.gov; Noggle.William@epamail.epa.gov; Chris Green; Jason

Glascock; Tony Schultz; Tara Tomaslewicz; Randy Boudreaux; Robert Berry

Subject:

RE: USCGC STORIS HAZMAT SURVEY

#### Attachments:

Mr. Beach and Ms. Dillard.

Encapsulated PCBs (page 1 of the report) become un-encapsulated when a vessel is dismantled, therefore this vessel would not meet the spirit or the terms of the TSCA PCB export ban. Our company would be more than happy to sit down with the USCG and try to determine a cost-effective fashion to dismantle this vessel in the U.S. If we had a facility on the West Coast (and we continue to look), it might, depending upon condition and extent of hazardous material, even be cost-effective to buy the Storis and still dismantle it to meet all U.S. environmental and safety regulations. Even if the US Government had to pay a nominal amount to ensure the vessel met the same fate (i.e. scrapped to U.S. environmental and safety laws and regulations) as the USCG buoy tenders (which are even older) that MARAD is selling for your agency out of the SBRF, it would be better than having this type of mess on the USCG and GSA's hands. Please let us know if we can be of any help; Mr. Boudreaux and Mr. Berry, whom I have cc'd, are EMR Southern Vice Presidents and co-manage the marine division.

#### Polly Parks

T: +1 (804)410-2168

M: +1 (703)338-6881

F: +1 (804)410-2168

E: poliy.parks@emrgroup.com

A: EMR USA - Southern, Washington DC Office, 216 Spotswood Lane, Coloniał Beach, VA 22443 usa.emrgroup.com

From: Beach, Jeff L CIV [mailto:Jeff.L.Beach@usog.mll]

Sent: Fri 10/25/2013 10:21 AM

To: Polly Parks

Cc: TONYA.DILLARD@gsa.gov

Subject: FW: USCGC STORIS HAZMAT SURVEY

Ms. Parks

Per your request the HAZMAT reports for CGC STORIS are attached.

Jeff Beach, CPPM
Manager of Retired CG Boats & Decommissioned Cutters
USCG Headquarters @ ST "E" Campus
(202) 372-3646

----Original Message-----From: Beach, Jeff L CIV

Sent: Thursday, October 24, 2013 11:10 AM

To: 'rollins.christopher@epa.gov'

Subject: FW: USCGC STORIS HAZMAT SURVEY

STORIS documentation as requested

Jeff Beach, CPPM

Manager of Retired CG Boats & Decommissioned Cutters USCG Headquarters @ ST "E" Campus (202) 372-3646



Safety Office, MS#1 U.S. Coast Guard YARD 2401 Hawkins Point Road Beltimors, MD 21228-1797 Staff Symbol: sm-110 Phone: (410) 638-3772 Fac: (410) 638-3779 Email: Robert.D.McMenamin@usog.mli

1/17/2007 5090

## MEMORANDUM

From:

Robert D. McMenamin

Environmental Protection Specialist

To:

Commandant, CG-453

Subj:

CGC STORIS HAZMAT CLEAN-UP

2. I trust this information will be sufficient for your purposes, but if you have any questions concerning this survey, please contact me.

Robert OMMcMenamin

Copy:

CO, CGC STORIS

Commandant, CG-842

Chief, Planning and Estimating, CG YARD